

On Scene Photos
Courtesy of the Pilot



Figure 1: Helicopter Cabin



Figure 2: Severed Tailboom

On Scene Photos
Courtesy of the Pilot



Figure 3: Left Side of Helicopter



Figure 4: Tailboom and Empennage

End. - Submitted by: Samantha Link