

Photos of N1953B
Courtesy of the Federal Aviation Administration



Figure 1: Airplane on Runway

Photos of N1953B
Courtesy of the Federal Aviation Administration



Figure 2: View of Vertical Stabilizer and Rudder

Photos of N1953B
Courtesy of the Federal Aviation Administration



Figure 3: Damage to the Lower Cowling near the Firewall



Figure 4: Damage to Wing Root

Photos of N1953B
Courtesy of the Federal Aviation Administration



Figure 5: Damage to Left Wingtip

END.

Submitted by Samantha Link