


ANC24LA068

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of accident airplane at the accident site (Courtesy of Operator)



Photograph 2 - Image of fuselage, empennage, left wing, and left float (Courtesy of Operator)