



Photo 1 – View of the accident site.



Photo 2 - View of the accident site.



Photo 3 - View of the accident site.



Photo 4 - View of the accident site.



Photo 5 - View of the accident site.



Photo 6 – Aerial view of the accident site.



Photo 7 – View of the recovered wreckage.



Photo 8 - View of the recovered wreckage.



Photo 9 - View of the recovered flight control cables.



Photo 10 - View of the recovered wreckage.



Photo 11 - View of the recovered wreckage.



Photo 12 - View of the recovered wreckage.



Photo 13 - View of the recovered wreckage and engine parts.



Photo 14 - View of the recovered propellers and wreckage.



Photo 15 - View of the recovered propellers and wreckage.



Photo 16 - View of the recovered wreckage.



Photo 17 - View of the recovered seatbelt clasp.



Photo 18 – Portion of canopy structure. Courtesy of California Rehabilitation Center



Photo 19 - Portion of canopy structure. Courtesy of California Rehabilitation Center



Photo 20 - Portion of canopy structure. Courtesy of California Rehabilitation Center