



Photo 1 – View of the recovered wreckage.



Photo 2 - View of the recovered wreckage.



Photo 3 – View of the wreckage at the accident site. Courtesy of Alaska State Troopers