


CEN23FA360

INVESTIGATION PHOTOGRAPHS

PG 1 OF 7



Photograph 1 - Accident airplane (Courtesy of Oklahoma City Sherriff Department)



Photograph 2 - Accident airplane (Courtesy of NTSB)



Photograph 3 - Accident airplane (Courtesy of NTSB)



Photograph 4 - Accident airplane (Courtesy of NTSB)



Photograph 5 - Airplane instrument panel (Courtesy of NTSB)



Photograph 6 - Airplane fuel selector valve (Courtesy of NTSB)