



Photo 1 – View of the main wreckage.



Photo 2 - View of the main wreckage.



Photo 3 – Tire marks / tracks adjacent to the runway from main wreckage.



Photo 4 - Tire marks / tracks adjacent to and on the runway.



Photo 5 - Tire marks / tracks adjacent to and on the runway.



Photo 6 - Tire marks / tracks on the runway.



Photo 7 – Main wreckage, left engine and propeller.



Photo 8 - Main wreckage and right engine.



Photo 9 – Right Propeller



Photo 10 -Forward part of the fuselage.



Photo 11 – Outboard portions of the tailwheel locking pin.



Photo 12 - Forward part of the fuselage, and cockpit area.



Photo 13 – Aft portion of the fuselage, including the tailwheel insert.



Photo 14 – Tailwheel locking mechanism.