

Photo 1 – Satellite view of debris area



Photo 2 – Cockpit and cabin wreckage



Photo 3 – Part of a wing



Photo 4 – Burned house



Photo 5 – Part of the left wing



Photo 6 – Part of a vertical stab



Photo 7 – Left engine