



Photo 1 – Side View of Accident Airplane (Photo Courtesy of FAA)



Photo 2 – Accident Site (Photo Courtesy of FAA)



Actual landing spot. It's a dirt parking lot and the strip was dark from a water truck spray-down, which he mistook for the runway. There were no cars there.

Pink line represents power lines between Palo Verde rd and the small water treatment building right there.

Photo 3 – Diagram of Accident Site (Photo Courtesy of the FAA)