



# The National Transportation Safety Board

Office of Aviation Safety  
Central Region  
Memorandum for the Record  
Witness Location and Witness  
Statement Summary  
CEN22LA129  
Franklin, Indiana  
February 21, 2022

A witness to the accident reported that he was in a hangar at the Franklin airport (3FK) visiting with some friends when we heard what appeared to be at that time and engine run up. A few moments later he heard an impact not knowing what it was at that time. We went outside to look around and noticed it was a plane that hit to the northeast of the hangar.

He proceeded to the accident site to help, and the pilot told him that “he stalled the airplane while doing touch and goes.” The witness immediately requested emergency assistance.

The pilot was transported to the hospital.



- ★ Aircraft Location  
Approximately  
600 feet from the  
end of the  
runway.
- ★ Hangar location of the  
Witness at the time  
Of the accident.

Alexander Lemishko



Senior Air Safety Investigator  
NTSB Central Region Aviation