



FRA Signal Inspection Reporting Test Locations with FRA Tests (Short-term)

Current User: ENCO231@UPCORP.AD.UPRR.COM

Page Generated: 09/09/2022 16:10

▼ Your selection criteria (Click the arrow to hide/unhide this section)

Subdivision: YUMA SUB **MP:** 648.009 **Signal MP:** 648.020 **Segment:** 6692-0nbsp; **Track:** NO 2 **ZTS:** ENM
Sys No: 1106507 **County:** IMPERIAL **State:** CA **Asset Type:** CP/SIGNAL **Asset Desc:** SP648 MAIN (PRINT MP648.02) **From:** 09/08/2021 **To:** 09/08/2022 **Frequency:** ALL **Include Unscheduled:** Yes

▼ Result Code legend (Click the arrow to hide/unhide this section)

Test Result Codes

- C** - Test complete. Equipment in satisfactory condition.
- A** - Adjustment made and test complete. Equipment in satisfactory condition.
- R** - Repairs or replacement needed.
- S** - Repairs or replacement made. Equipment in satisfactory condition.
- O** - Out of service.

Other Codes

- u** - Unscheduled Test

No.	Test Date	Date Found Requiring Repair	Test Frequency	FRA Rule	FRA Test Description	Equipment Tested or Inspected	Train Detection Device Name	Method Used	Pre-determined Time	Actual Time	Test Result	Test Comment	Tested By
1	07/25/2022		Quarterly	236.107	Grounds	B12					C		
2	07/25/2022		Quarterly	236.107	Grounds	B24					C		
3	05/11/2022	u	Unscheduled	236.107	Grounds	B24					S	REPAIRED/REPLACED LENS/LIGHT UNIT	
4	05/03/2022		Quarterly	236.107	Grounds	B12					C		
5	05/03/2022		Quarterly	236.107	Grounds	B24					C		
6	02/07/2022		Quarterly	236.107	Grounds	B12					C		
7	02/07/2022		Quarterly	236.107	Grounds	B24					C		
8	11/15/2021		Quarterly	236.107	Grounds	B12					C		
9	11/15/2021		Quarterly	236.107	Grounds	B24					C		

Print

Back