

All Rail Defects

Line Segment: 477

Milepost Begin: 97

From Date: 10/15/2022

Defect Type: Detector Car Only

Milepost End: 117

To Date: 10/15/2023

Line Segment	Defect Milepost	Test Date	Car Number	Track Number	Track Type	Rail Position	Defect Seq. Nbr	Defect Type	Defect Size	Correction Date	Corrective Action
477	104.066	2023-01-27	HRZ181	1	M	LEFT	27	Orgotherm Weld	30.00	2023/01/27 2023/02/22	C R
477	110.516	2023-01-27	HRZ181	1	M	RIGHT	28	Detail Fracture	25.00	2023/01/27 2023/02/21	C R
477	113.421	2023-01-27	HRZ181	1	M	LEFT	29	Orgotherm Weld	25.00	2023/01/27 2023/03/02	C R
477	113.424	2023-01-27	HRZ181	1	M	LEFT	30	Detail Fracture	30.00	2023/01/27 2023/03/02	C R
477	109.668	2022-11-10	HRZ190	7401	5	LEFT	317	Shelled/Spalled/Corrugated Rail	36.00	2022/11/10 2023/04/29	N R
477	109.074	2022-11-10	HRZ190	7401	5	RIGHT	318	Detail Fracture	30.00	2022/11/10 2023/04/20	C R
477	104.168	2022-11-10	HRZ190	1	M	RIGHT	319	Boutet Weld	30.00	2022/11/10 2022/11/23	C R
477	113.336	2023-07-19	HRZ189	1	M	RIGHT	351	Shelled/Spalled/Corrugated Rail	120.00	2023/08/03	R
477	113.467	2023-07-19	HRZ189	1	M	RIGHT	352	Pressure Electric Weld	15.00	2023/07/19 2023/07/25	C R
477	113.479	2023-07-19	HRZ189	1	M	LEFT	353	Pressure Electric Weld	20.00	2023/07/19 2023/07/25	C R
477	113.562	2023-07-19	HRZ189	1	M	LEFT	354	Orgotherm Weld	15.00	2023/07/19 2023/07/26	C R
477	113.599	2023-07-19	HRZ189	1	M	RIGHT	355	Shelled/Spalled/Corrugated Rail	36.00	2023/08/20 2023/10/12	N R
477	114.135	2023-07-19	HRZ189	1	M	LEFT	356	Boutet Weld	15.00	2023/07/19 2023/07/25	C R

As of: October 18, 2023

Data Source : TRPT\_RAIL\_DEFECT

Report Id : RDFT1

Report Name : All Rail Defects