

Photo 1 – Google Earth overlay of final segment track log recorded on Appareo Stratus 3



Photo 2 - Recovery of airplane out of Lake Mead.



Photo 3 - Oil filter adapter housing and filter.



Photo 4 - Oil filter adapter housing gasket.




Photo 5 - Additional example of Mill Creek, California accident oil filter adapter attached to similar engine.