



Car Movement Report - CANADIAN PACIFIC

Thursday, June 27, 2024

REPORT: 179A CAR: 108 TESTMODE: S&V

REGION: EASTERN					DIVISION: GLENWOOD								
SUBDIVISION: CRG, CARRINGTON					PROV/ST: NORTH DAKOTA								
(CT)	LOCATION				MILES		TIME(Minutes)						REMARKS/ TRAFFIC COMMENT
M TIME	TRK	TRACK NAME	D	MILEPOST	TEST	RUN	TEST	RUN	TRFC	RRDEL	RPR	SRS	
1 06:00	RD			340.73									CARRINGTON, ND
3 06:15	RD			340.73						15			SAFETY/JOB BRIEFING
4 07:45	RD		D	316.00				90					ON ROAD
3 07:50	RD		D	316.00						5			DISP ORDERS/PERMIT
4 08:00	SI		D	316.00		0.00		10					ON TRACK
5 09:10	SI	SINGLE MAIN	U	334.40	18.40		70						SINGLE MAIN
3 10:25	SI	SINGLE MAIN	U	334.40					75				TRAFFIC/CP 8762 WEST
3 10:30	SI	SINGLE MAIN	U	334.40						5			DISP RTC DELAY
5 11:20	SI	SINGLE MAIN	U	340.73	6.33		50						SINGLE MAIN
4 13:30	RD		D	286.95				130					ON ROAD
3 13:40	RD		D	286.95						10			MAINTENANCE CREW
3 13:45	RD		D	286.95						5			DISP ORDERS/PERMIT
5 14:00	SI	SINGLE MAIN	D	284.00	2.95		15						SINGLE MAIN
4 14:10	SI		D	284.00		0.00		10					ON TRACK
3 14:15	SI		D	284.00						5			DISP ORDERS/PERMIT
4 14:30	RD		D	284.00				15					ON ROAD
2 14:30	RD		D	284.00									VALLEY CITY,ND
Location Totals:					27.68	0.00	135	255	75	45	0	0	(Minutes)
Report Totals:					27.68	0.00	135	255	75	45	0	0	(Minutes)

RR Totals		SRS Totals	
TIME	MILES	TIME	MILES
02:15	27.68	TESTING	00:00 0.00
04:15	0.00	RUNLT	00:00 0.00
01:15		TRAFFIC	
00:45		OTHER	00:00
08:30	27.68	TOTALS	00:00 0.00

TEST SYSTEMS:	ITS	VTS	XFIRE	JBCD
INSTALLED:	Yes	Yes	Yes	Yes
TESTED WITHOUT:	0	0	0	0

Defects Found: 0
 Estimated Stops: 14
 Estimated Picks: 6
 Goal Miles: 27

LESS THAN 8 HRS SERV TO RR CODE:

TOTAL RR SERVICE TIME: 08:30
 RR SERVICE TIME - RR TEST TIME: 06:15
 SPERRY HOLD:
 SPERRY REPAIR: 00:00
 TOTAL HOURS WORKED: 08:30

END OF SERVICE REMARK:



Car Movement Report - CANADIAN PACIFIC

Thursday, June 27, 2024

REPORT: 179A CAR: 108

Chief Operator:
Waite, Chris



RR Representative:
CHRIS WAITE
PILOT





Defective Rail Report - CANADIAN PACIFIC

Thursday, June 27, 2024

REPORT: 179A CAR: 108

REGION: EASTERN										DIVISION: GLENWOOD									
SUBDIVISION: CRG, CARRINGTON										PROV/ST: NORTH DAKOTA									
DEFECT		LOCATION										RAIL INFO				REMARK			
NUM	TYPE	SIZE	MILEPOST	TRK	TRACK NAME	R/L	LATITUDE	LONGITUDE	WGT	PRO	TF	RC	AL	YEAR	MFG				

Total Defects Found in this location: 0

Defective Rail Summary

	BBJ	BBO	BHJ	BHO	BR	CHO	CRO	DWF	DWL	DWP	EBF	HSJ	HSJ	HWJ	HWOPRJ	PRO	SSC	SWJ	SWO	TDC	TDD	TDT	VSH	VSJ	Totals				
RIGHT	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0					0
LEFT	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0					0
TOTAL	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0					0

Chief Operator:
Waite, Chris



RR Representative:
CHRIS WAITE
PILOT



This document and all services and/or products provided in connection with this document and all future sales are subject to and shall be governed by the Sperry Standard Sale and Service Terms in effect when the services and/or products are ordered. THOSE TERMS ARE AVAILABLE AT WWW.SPERRYRAIL.COM/SERVICETERMS, ARE EXPRESSLY INCORPORATED BY REFERENCE INTO THIS DOCUMENT AND SHALL SUPERSEDE ANY CONFLICTING TERMS IN ANY OTHER DOCUMENT (EXCEPT WHERE EXPRESSLY AGREED OTHERWISE IN THAT OTHER DOCUMENT).



Defect Summary / Remedial Action Report - CANADIAN PACIFIC

Thursday, June 27, 2024

REPORT: 179A CAR: 108

REGION: EASTERN				DIVISION: GLENWOOD				
SUBDIVISION: CRG, CARRINGTON				PROV/ST: NORTH DAKOTA				
LOCATION				DEFECT			REMEDIAL ACTION	DATE COMPLETED
TRACK NAME	TRK	MILEPOST	*SIDE	NUM	TYPE	SIZE		

Total Defects Found in this location: 0

A copy of this inspection record must be retained by the Track Maintenance Supervisor for at least 2 years after the inspection and for 1 year after the remedial action is taken.

*SIDE is determined while facing in the direction of increasing mileposts.

RAILWAY EMPLOYEE ACCOMPANYING RAIL TESTER: _____
Signature



Rail Test Exception Report - CANADIAN PACIFIC

Thursday, June 27, 2024

REPORT: 179A CAR: 108

REGION: EASTERN				DIVISION: GLENWOOD			
SUBDIVISION: CRG, CARRINGTON				PROV/ST: NORTH DAKOTA			
LOCATION				CONDITION			
TRACK	FROM MP	TO MP	SIDE	POSITION	STATUS	REASON CODE	COMMENTS

No Test Exceptions in this Location

Chief Operator:
Waite, Chris



RR Representative:
CHRIS WAITE
PILOT





Car Movement Report - CANADIAN PACIFIC

Wednesday, June 26, 2024

REPORT: 178A CAR: 108 TESTMODE: S&V

REGION: EASTERN					DIVISION: GLENWOOD									
SUBDIVISION: CRG, CARRINGTON					PROV/ST: NORTH DAKOTA									
(CT)	LOCATION				MILES		TIME(Minutes)						REMARKS/ TRAFFIC COMMENT	
M TIME	TRK	TRACK NAME	D	MILEPOST	TEST	RUN	TEST	RUN	TRFC	RRDEL	RPR	SRS		
1	06:00	RD			367.94									CARRINGTON, ND
3	06:15	RD			367.94					15				SAFETY/JOB BRIEFING
4	07:15	RD	U		367.94			60						ON ROAD
3	08:20	RD	U		367.94				65					TRAFFIC/CP 8809 WEST
3	09:00	RD	U		367.94				40					TRAFFIC/CP 8915 WEST
3	09:10	RD	U		367.94					10				DISP ORDERS/PERMIT
4	09:15	SI	U		367.94		0.00	5						ON TRACK
5	10:15	SI		SINGLE MAIN	D	358.05	9.89		60					SINGLE MAIN
3	10:35	SI		SINGLE MAIN	D	358.05				20				TRAFFIC/KCS 4571 EAST
3	10:50	SI		SINGLE MAIN	D	358.05					15			DISP ORDERS/PERMIT
5	11:20	SI		SINGLE MAIN	D	354.56	3.48		30					SINGLE MAIN
3	12:45	SI		SINGLE MAIN	D	354.56				85				TRAFFIC/CP 7002 WEST
3	13:00	SI		SINGLE MAIN	D	354.56					15			DISP ORDERS/PERMIT
5	13:10	SI		SINGLE MAIN	D	353.26	1.31		10					SINGLE MAIN
3	13:20	SI		SINGLE MAIN	D	353.26					10			OTHER RR DELAY/HT DIAMOND
5	14:30	SI		SINGLE MAIN	D	340.73	12.53		70					SINGLE MAIN
4	14:50	SI			D	340.73		0.00		20				ON TRACK
4	15:30	RD			D	340.73				40				ON ROAD
2	15:30	RD			D	340.73								CARRINGTON,ND
Location Totals:					27.21	0.00	170	125	210	65	0	0		(Minutes)
Report Totals:					27.21	0.00	170	125	210	65	0	0		(Minutes)



Car Movement Report - CANADIAN PACIFIC

Wednesday, June 26, 2024

REPORT: 178A CAR: 108

(CT) M TIME	LOCATION				MILES		TIME(Minutes)						REMARKS/ TRAFFIC COMMENT
	TRK	TRACK NAME	D	MILEPOST	TEST	RUN	TEST	RUN	TRFC	RRDEL	RPR	SRS	

RR Totals		SRS Totals			
TIME	MILES		TIME	MILES	
02:50	27.21	TESTING	00:00	0.00	
02:05	0.00	RUNLT	00:00	0.00	
03:30		TRAFFIC			
01:05		OTHER	00:00		
09:30	27.21	TOTALS	00:00	0.00	

TEST SYSTEMS:	ITS	VTS	XFIRE	JBCD
INSTALLED:	Yes	Yes	Yes	Yes
TESTED WITHOUT:	0	0	0	0

Defects Found: 1
 Estimated Stops: 29
 Estimated Picks: 10
 Goal Miles: 27

LESS THAN 8 HRS SERV TO RR CODE:


TOTAL RR SERVICE TIME: 09:30
 RR SERVICE TIME - RR TEST TIME: 06:40
 SPERRY HOLD:
 SPERRY REPAIR: 00:00
 TOTAL HOURS WORKED: 09:30

END OF SERVICE REMARK:

Chief Operator:
 Waite, Chris



RR Representative:
 SCOTT SOBANIA
 PILOT



This document and all services and/or products provided in connection with this document and all future sales are subject to and shall be governed by the Sperry Standard Sale and Service Terms in effect when the services and/or products are ordered. THOSE TERMS ARE AVAILABLE AT WWW.SPERRYRAIL.COM/SERVICETERMS, ARE EXPRESSLY INCORPORATED BY REFERENCE INTO THIS DOCUMENT AND SHALL SUPERSEDE ANY CONFLICTING TERMS IN ANY OTHER DOCUMENT (EXCEPT WHERE EXPRESSLY AGREED OTHERWISE IN THAT OTHER DOCUMENT).



Defective Rail Report - CANADIAN PACIFIC

Wednesday, June 26, 2024

REPORT: 178A CAR: 108

REGION: EASTERN										DIVISION: GLENWOOD									
SUBDIVISION: CRG, CARRINGTON										PROV/ST: NORTH DAKOTA									
DEFECT			LOCATION							RAIL INFO					REMARK				
NUM	TYPE	SIZE	MILEPOST	TRK	TRACK NAME	R/L	LATITUDE	LONGITUDE	WGT	PRO	TF	RC	AL	YEAR		MFG			
192	DWP	10	354.574	SI	SINGLE MAIN	L	47.47193811	-99.16026714	132	RE	NN	W	T	1971		ILL			

Total Defects Found in this location: 1

Defective Rail Summary

	BBJ	BBO	BHJ	BHO	BR	CHO	CRO	DWF	DWL	DWP	EBF	HSJ	HSJ	HWJ	HWO	PRJ	PRO	SSC	SWJ	SWO	TDC	TDD	TDT	VSH	VSJ	Totals	
RIGHT	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
LEFT	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TOTAL	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1

Chief Operator:
Waite, Chris



RR Representative
SCOTT SOBANIA
PILOT



This document and all services and/or products provided in connection with this document and all future sales are subject to and shall be governed by the Sperry Standard Sale and Service Terms in effect when the services and/or products are ordered. THOSE TERMS ARE AVAILABLE AT WWW.SPERRYRAIL.COM/SERVICETERMS, ARE EXPRESSLY INCORPORATED BY REFERENCE INTO THIS DOCUMENT AND SHALL SUPERSEDE ANY CONFLICTING TERMS IN ANY OTHER DOCUMENT (EXCEPT WHERE EXPRESSLY AGREED OTHERWISE IN THAT OTHER DOCUMENT).



Defect Summary / Remedial Action Report - CANADIAN PACIFIC

Wednesday, June 26, 2024

REPORT: 178A CAR: 108

REGION: EASTERN				DIVISION: GLENWOOD				
SUBDIVISION: CRG, CARRINGTON				PROV/ST: NORTH DAKOTA				
LOCATION				DEFECT			REMEDIAL ACTION	DATE COMPLETED
TRACK NAME	TRK	MILEPOST	*SIDE	NUM	TYPE	SIZE		
SINGLE MAIN	SI	354.574	L	192	DWP	10	Protection Code 22	

Total Defects Found in this location: 1

A copy of this inspection record must be retained by the Track Maintenance Supervisor for at least 2 years after the inspection and for 1 year after the remedial action is taken.

*SIDE is determined while facing in the direction of increasing mileposts.

RAILWAY EMPLOYEE ACCOMPANYING RAIL TESTER: _____
Signature



Rail Test Exception Report - CANADIAN PACIFIC

Wednesday, June 26, 2024

REPORT: 178A CAR: 108

REGION: EASTERN				DIVISION: GLENWOOD			
SUBDIVISION: CRG, CARRINGTON				PROV/ST: NORTH DAKOTA			
LOCATION				CONDITION			
TRACK	FROM MP	TO MP	SIDE	POSITION	STATUS	REASON CODE	COMMENTS

No Test Exceptions in this Location

Chief Operator:
Waite, Chris



RR Representative:
SCOTT SOBANIA
PILOT





Car Movement Report - CANADIAN PACIFIC

Friday, April 12, 2024

REPORT: 103A CAR: 108 TESTMODE: S&V

REGION: EASTERN					DIVISION: GLENWOOD									
SUBDIVISION: CRG, CARRINGTON					PROV/ST: NORTH DAKOTA									
(CT)	LOCATION				MILES		TIME(Minutes)						REMARKS/ TRAFFIC COMMENT	
M TIME	TRK	TRACK NAME	D	MILEPOST	TEST	RUN	TEST	RUN	TRFC	RRDEL	RPR	SRS		
1	06:30	RD			348.83									CARRINGTON, ND
3	06:45	RD			348.83					15				SAFETY/JOB BRIEFING
4	07:10	RD	U		348.83			25						ON ROAD
3	07:25	RD	U		348.83					15				DISP ORDERS/PERMIT
4	07:35	SI	U		348.83		0.00	10						ON TRACK
5	08:25	SI		SINGLE MAIN	D	340.73	8.10		50					SINGLE MAIN
4	08:40	SD	U		342.84		2.11	15						ON TRACK
5	08:45	SD		SIDING	D	342.77	0.07		5					DRY LAKE SIDING
3	08:50	SD		SIDING	D	342.77				5				OTHER RR DELAY/EIC LINING SWITCH
5	09:15	SD		SIDING	D	340.73	2.04		25					DRY LAKE SIDING COMPLETE
5	10:15	SI		SINGLE MAIN	D	330.78	9.95		60					SINGLE MAIN
3	10:25	SI		SINGLE MAIN	D	330.78				10				DISP ORDERS/PERMIT
5	10:35	SI		SINGLE MAIN	D	329.18	1.59		10					SINGLE MAIN
4	10:55	SI	U		330.83		1.65	20						ON TRACK
5	11:00	SD		SIDING	D	330.76	0.07		5					KENSAL SIDING
3	11:05	SD		SIDING	D	330.76				5				OTHER RR DELAY/EIC LINING SWITCH
5	11:30	SD		SIDING	D	329.18	1.57		25					KENSAL SIDING COMPLETE
5	12:15	SI		SINGLE MAIN	D	321.00	8.18		45					SINGLE MAIN
3	13:15	SI		SINGLE MAIN	D	321.00				60				TRAFFIC/CP 9802 EAST
3	14:05	SI		SINGLE MAIN	D	321.00				50				TRAFFIC/CP 9781 WEST
4	14:45	RD			321.00			40						ON ROAD
2	14:45	RD			321.00									VALLEY CITY,ND
Location Totals:					31.59	3.76	225	110	110	50	0	0		(Minutes)
Report Totals:					31.59	3.76	225	110	110	50	0	0		(Minutes)



Car Movement Report - CANADIAN PACIFIC

Friday, April 12, 2024

REPORT: 103A CAR: 108

(CT) M TIME	LOCATION				MILES		TIME(Minutes)						REMARKS/ TRAFFIC COMMENT
	TRK	TRACK NAME	D	MILEPOST	TEST	RUN	TEST	RUN	TRFC	RRDEL	RPR	SRS	

RR Totals		SRS Totals	
TIME	MILES	TIME	MILES
03:45	31.59	TESTING	00:00 0.00
01:50	3.76	RUNLT	00:00 0.00
01:50		TRAFFIC	
00:50		OTHER	00:00
08:15	35.34	TOTALS	00:00 0.00

TEST SYSTEMS:	ITS	VTS	XFIRE	JBCD
INSTALLED:	Yes	Yes	Yes	Yes
TESTED WITHOUT:	0	0	0	0

Defects Found: 1
 Estimated Stops: 38
 Estimated Picks: 17
 Goal Miles: 27

LESS THAN 8 HRS SERV TO RR CODE:
 TOTAL RR SERVICE TIME: 08:15
 RR SERVICE TIME - RR TEST TIME: 04:30
 SPERRY HOLD:
 SPERRY REPAIR: 00:00
 TOTAL HOURS WORKED: 08:15

END OF SERVICE REMARK:

Chief Operator:
Sobania, Shawn



RR Representative:
CHRIS WAITE
PILOT





Defective Rail Report - CANADIAN PACIFIC

Friday, April 12, 2024

REPORT: 103A CAR: 108

REGION: EASTERN										DIVISION: GLENWOOD									
SUBDIVISION: CRG, CARRINGTON										PROV/ST: NORTH DAKOTA									
DEFECT			LOCATION							RAIL INFO					REMARK				
NUM	TYPE	SIZE	MILEPOST	TRK	TRACK NAME	R/L	LATITUDE	LONGITUDE	WGT	PRO	TF	RC	AL	YEAR		MFG			
107	CHO	8	338.767	SI	SINGLE MAIN	R	47.36130287	-98.86474415	115	RE	NN	W	T	1949		ILL			

Total Defects Found in this location: 1

Defective Rail Summary

	BBJ	BBO	BHJ	BHO	BR	CHO	CRO	DWF	DWL	DWP	EBF	HSJ	HSJ	HWJ	HWO	PRJ	PRO	SSC	SWJ	SWO	TDC	TDD	TDT	VSH	VSJ	Totals	
RIGHT	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
LEFT	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
TOTAL	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1

Chief Operator:
Sobania, Shawn



RR Representative:
CHRIS WAITE
PILOT



This document and all services and/or products provided in connection with this document and all future sales are subject to and shall be governed by the Sperry Standard Sale and Service Terms in effect when the services and/or products are ordered. THOSE TERMS ARE AVAILABLE AT WWW.SPERRYRAIL.COM/SERVICETERMS, ARE EXPRESSLY INCORPORATED BY REFERENCE INTO THIS DOCUMENT AND SHALL SUPERSEDE ANY CONFLICTING TERMS IN ANY OTHER DOCUMENT (EXCEPT WHERE EXPRESSLY AGREED OTHERWISE IN THAT OTHER DOCUMENT).



Defect Summary / Remedial Action Report - CANADIAN PACIFIC

Friday, April 12, 2024

REPORT: 103A CAR: 108

REGION: EASTERN				DIVISION: GLENWOOD				
SUBDIVISION: CRG, CARRINGTON				PROV/ST: NORTH DAKOTA				
LOCATION				DEFECT			REMEDIAL ACTION	DATE COMPLETED
TRACK NAME	TRK	MILEPOST	*SIDE	NUM	TYPE	SIZE		
SINGLE MAIN	SI	338.767	R	107	CHO	8	Protection Code 23	

Total Defects Found in this location: 1

A copy of this inspection record must be retained by the Track Maintenance Supervisor for at least 2 years after the inspection and for 1 year after the remedial action is taken.

*SIDE is determined while facing in the direction of increasing mileposts.

RAILWAY EMPLOYEE ACCOMPANYING RAIL TESTER: _____
Signature



Rail Test Exception Report - CANADIAN PACIFIC

Friday, April 12, 2024

REPORT: 103A CAR: 108

REGION: EASTERN				DIVISION: GLENWOOD			
SUBDIVISION: CRG, CARRINGTON				PROV/ST: NORTH DAKOTA			
LOCATION				CONDITION			
TRACK	FROM MP	TO MP	SIDE	POSITION	STATUS	REASON CODE	COMMENTS

No Test Exceptions in this Location

Chief Operator:
Sobania, Shawn



RR Representative:
CHRIS WAITE
PILOT

