

ANC25LA097

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - View of helicopter where it came to rest (Courtesy of operator)**



**Photograph 2 - View of separated main rotor blades. (Courtesy of operator)**