



Airworthiness - Photo 16. View of the seat back structure of the aft-facing passenger seats in row 2. Note that the structure is bulged outward (forward relative to their normal installation in airplane). (NTSB-A2)