



Survival Factors Group. Photo 9. Close-up photo of puncture to gas tank of GMC Sierra. (NTSB Photograph taken on 08/08/10)