



Survival Factors Group Photo 25. View of undamaged rear emergency exit window on 2003 Bluebird 71-passenger school bus showing width of raised latch tab at base of window.