



Vehicle Attachment 11a
Maintenance Record of the Bus Involved in the Hospital Parking Lot Accident
(Example of a page from Copeland Bus Services spiral bound notebook)

Gray Summit, MO
HWY-10-MH-018

(2 pages)

#7 2000 AA

Fuel PF7777
BF1252
OIL AT595
BELT K080685
L039841

8-24-07	Full serv.	128815
8-24-07	RR calx Pads	129216
9-18-07	LUBC	130362
10-4-09	Full serv	132015
11-12-09	LUBC	133656
12-15-09	Full serv + Fuel Filters	135728
1-28-10	LUBC + OIL	137429
2-19-10	Full serv	139046
3-11-10	LUBC	140585
3-18-10	R Tie rod + 3 BC 1 u clamp	141018
4-7-10	Full serv.	142156
4-22-10	2 ^{new} tires + align	143242
4-29-10	LUBC	143746
5-3-10	Reducer in FR muffer	143782
6-11-10	Full service	145824