

Promech Air
Ketchikan, AK
June 25, 2015
ANC15MA041

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.**

ATTACHMENT 14

Investigator Photos of Terrain Surrounding the Accident Location

4 Pages



Photo 1 – Terrain surrounding accident location



Photo 2 - Terrain surrounding accident location (wreckage circled in yellow)



Photo 3 - Terrain surrounding accident location (wreckage circled in yellow)



Photo 4 - Terrain surrounding accident location (wreckage circled in yellow)