



HIGHWAY ACCIDENT BRIEF PHOTOS

Alexandria, Virginia

HWY16SH025

(4 pages)



Photograph 1 – Showing the crash debris field and the rear of the GMC Yukon in the 8300 Block of Richmond Highway – facing north



Photograph 2 – *Showing the location of the fabric transfer from the pedestrian's jeans onto the pavement in the right through lane of travel*



Photograph 3 – Front passenger’s side corner of GMC Yukon showing damage to the headlight and hood