Survival Factors Factual Report

Photographs

Rochester, Indiana

HWY19MH003

(5 pages)

Photo #1 Looking northbound on State Road 25 at the approach to the mobile home park bus stop (Photo provided by the Indiana State Police)

Photo #2 Aerial view of crash scene showing the location of stopped school bus and the driveway where the pedestrians waited for the bus. (ISP photo)

Photo #3 Close-up of the driveway and the adjacent trailer where the pedestrians stood to wait for the school bus (ISP)

Photo #4 Aerial view looking northbound at the final rest position of the striking truck (ISP)

Photo #5 Photograph of incident school bus with warning lights activated

Photo #6 Incident school bus with warning lights activated and close-up of the deployed stop arm.

Photo #7 Photograph of an agricultural vehicle. (indicated by arrow) with similar coloring and shape to that of a school bus.