Regional Transit

Sacramento Regional Transit District
Repair Order

CAF

REPAIR ORDER NUMBER
220479

STRUCTURE CODE:	DATE	WRITTEN BY	MILEAGE	IDENTIFICATION NO.
(LRV) / OTHER	8-21-19	[redacted]	957,039	227

Scheduled	Non-Scheduled	Campaign	Road Call	Accident	Warranty
SC	(NS)	FT	RC	AC	WA

Describe Defect/Work to be Done:

Door B3 broken glass

To Be Filled Out By Maintainer

DATE	ACTION TAKEN/STATUS:	Hours	Clock #	Location Code	Purpose Code	Defect Code	Repair Code
8-22-19	Remove & Replace Door Glass B-3	4.0	2285	BX	C063	21	64
8-22-19	Remove & Replace Door Glass B-3	4.0	4287	BX	C063	21	64
	Total Hours To Be Filled Out By Supervisor →	8.0					

Parts or Materials Used

Quantity	Part Number	Parts Description	Serial Number ON	Serial Number OFF

WORK COMPLETED: [redacted] **DATE:** 8-23-19

Supervisor's Signature